

data/Expected_para_check_files/AMB-PRAMP-202101.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: Data check criteria not met

- missing vvc_code VVC123 BP sensor wasn't installed until June 2021. Complete monthly data submission starts in July 2021.

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202102.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: Data check criteria not met

- missing vvc_code VVC123 BP sensor wasn't installed until June 2021. Complete monthly data submission starts in July 2021.

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202103.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: Data check criteria not met

- missing vvc_code VVC123 BP sensor wasn't installed until June 2021. Complete monthly data submission starts in July 2021.

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202104.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: Data check criteria not met

- missing vvc_code VVC123 BP sensor wasn't installed until June 2021. Complete monthly data submission starts in July 2021.

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202105.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: Data check criteria not met

- missing vvc_code VVC123 BP sensor wasn't installed until June 2021. Complete monthly data submission starts in July 2021.

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202106-v01.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: Data check criteria not met

- missing vvc_code VVC123 BP sensor wasn't installed until June 2021. Complete monthly data submission starts in July 2021.

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202107.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: OK

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202108.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: OK

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202109.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: OK

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202110.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: OK

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202111.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: OK

station 1689: Data check criteria not met

- missing data for station 1689 Monitoring activities at Grimshaw starts in Dec 2021.

data/Expected_para_check_files/AMB-PRAMP-202112.xml:

station 1562: OK

station 1561: OK

station 1563: OK

station 1651: Data check criteria not met

- missing data for station 1651 Monitoring activities at Cadotte Lake station was completed in Nov 2021.

station 1689: OK